



Execute a program from the current probe position (zero point) (non-CAD)



NOTE: The model is shown only to give a clear representation of the process.



© 2014 Renishaw plc. All rights reserved.

Renishaw® is a registered trademark of Renishaw plc.

This document may not be copied or reproduced in whole or in part, or transferred to any other media or language, by any means, without the prior written permission of Renishaw.

The publication of material within this document does not imply freedom from the patent rights of Renishaw plc.

Disclaimer

Considerable effort has been made to ensure that the contents of this document are free from inaccuracies and omissions. However, Renishaw makes no warranties with respect to the contents of this document and specifically disclaims any implied warranties. Renishaw reserves the right to make changes to this document and to the product described herein without obligation to notify any person of such changes.

Trademarks

All brand names and product names used in this document are trade names, service marks, trademarks, or registered trademarks of their respective owners.

Execute a program from the current probe position (zero point) (non-CAD)

Care of equipment

Renishaw probes and associated systems are precision tools used for obtaining precise measurements and must therefore be treated with care.

Changes to Renishaw products

Renishaw reserves the right to improve, change or modify its hardware or software without incurring any obligations to make changes to Renishaw equipment previously sold.

Warranty

Renishaw plc warrants its equipment for a limited period (as set out in our Standard Terms and Conditions of Sale) provided that it is installed exactly as defined in associated Renishaw documentation.

Prior consent must be obtained from Renishaw if non-Renishaw equipment (e.g. interfaces and/or cabling) is to be used or substituted. Failure to comply with this will invalidate the Renishaw warranty.

Claims under warranty must be made from authorised service centres only, which may be advised by the supplier or distributor.

Trademarks

Windows 98, Windows XP, Windows 2000 and Windows NT are registered tradenames of the Microsoft Corporation.

IBM is the tradename of the International Business Machines Inc

All trademarks and tradenames are acknowledged.

Contents

1	Execute a program from the current probe position (non-CAD)	6
1.1	Tutorial pre-requisites.....	6
1.2	Tutorial objectives.....	6
2	Introduction.....	7
3	Start the CMM from current probe position	8
4	Create a temporary basic alignment	11
5	Create a precise alignment in CNC mode.....	15

1 Execute a program from the current probe position (non-CAD)

1.1 Tutorial pre-requisites

- The student should understand the contents of the 'Principles of part alignment' tutorial
- The student should have completed the following tutorials:
 - Part alignment - Plane, line and point
 - Part alignment - Plane and two circles
 - CNC part alignment
 - Cylindrical part alignment

1.2 Tutorial objectives

- Further exposure to CNC part programming from drawing definition
- Introduction to the concept of using a single co-ordinate system in a part program taken from an initial 'start' position




2 Introduction


This tutorial will explore an alternative method of part alignment which allows the programmer to create a fully or semi-automated part program. This method reduces the reliance on a CMM operator and will reduce the total run time of the program.

3 Start the CMM from current probe position

Create a new program.


Now add some simple operator prompts / instructions to ensure the probe can rotate and / or move to the rack and change probe






Enter a 'Label' and the point 'Nominal values' for the hole to be measured:

Point	Fresh_Air
Nominal	
X axis	0
Y axis	34.5
Z axis	-13
I	0
J	0
K	1






Code produced:

```
F(Fresh_Air)=FEAT/POINT,CART,0,34.5,-13,0,0,1
MEAS/POINT,F(Fresh_Air),0
ENDMES
```



Place origin on the point "Fresh_Air" in X,Y and Z:




Click: 'OK'.

The system now knows, very roughly, where the part is.



Execute a program from the current probe position (non-CAD)

4 Create a temporary basic alignment

At this point go into CNC mode.





Now change tool 'Settings' to allow the system to measure the hole without crashing:




Code produced:

```
SNSET/DEPTH,3
SNSET/CLRSRF,15
SNSET/APPRCH,2
SNSET/RETRCT,1.5
SNSET/SEARCH,3
```




Enter the nominal data for the hole:


Circle	CIR_001				
Report	Actual	Nominal	Low tol	High tol	
X axis	0	0			
Y axis	0	34.5			
Z axis	0	-10			
I	0	0			
J	0	0			
K	1	1			
Diameter	5	7			




Click 'Apply' then 'OK'. The CMM will now measure the hole.




Place origin in hole:




Now translate the origin to the correct drawing position:





Click: 'Move'.




Select: 'Absolute'.

NOTE: Alternatively press the 'Take Point' button on the MCU.

Enter the desired co-ordinates into the 'Target' boxes and then click 'OK'.

Alternatively click the 'Teach' button to learn the current position of the probe.



Code generated in program:

000023 ► GOTO/CART,0,34.5,10

The system now knows **approximately** where the part is located on the CMM, but it has **NO** idea of it's orientation.



Execute a program from the current probe position (non-CAD)

5 Create a precise alignment in CNC mode


From this point a correct part alignment can be made. The tool 'Approach' and 'Retract' settings should also be increased as the orientation of the part is still unknown.

SNSET/APPRCH,10


SNSET/RETRCT,10




Take eight points on the plane:



Click: 'Apply' to complete the measuring cycle.




Click: 'Datum'.



Select: 'One Axis'.

Give the alignment a meaningful label.





Enter a label for the feature as given on the drawing i.e. overwrite any existing

In this case the primary axis is normal to the measured plane and is in Z.

An origin on Z can also be set at this point.

GUIDANCE NOTE: When using head touches it is advisable that the approach is reduced to 2 mm as 10 mm is too large for a head swing.





Enter a 'Label' and the circle 'Nominal' data:

Check: Inner / outer.

Circle	DATUM_X_Y					Inner	Status	Error
Report	Actual	Nominal	Low tol	High tol	Deviation			
X axis	0	0			0			
Y axis	0	0			0			
Z axis	0	-4			4			
I	0	0						
J	0	0						
K	1	1						
Diameter	5	80			-75			
Circularity								


Execute a program from the current probe position (non-CAD)




Select: 'Apply' to complete the measuring cycle.


Click 'Move' then select 'Absolute' or alternatively use the MCU to manually position the probe and then press the 'Take Point' button.

Enter the co-ordinates to move the probe to a position above the circle to inspect:



Change 'Approach' and 'Retract' settings to 1.5 mm.





Enter a 'Label' and the circle 'Nominal' data:

Circle	DAT_X_CIR2					Inn
Report	Actual	Nominal	Low tol	High tol	Deviation	Status
X axis	24.395	24.395			-0	
Y axis	24.395	24.395			0	
Z axis	-13	-10			-0	
I	0	0				
J	0	0				
K	1	1				
Diameter	7	7			-0	


Click: 'Add Touches'.





Arc: PArc3
PTMEAS/CART,27.895,24.395,-10,-1,0,0
PTMEAS/CART,26.87,26.87,-10,-0.707,-0.707,0
PTMEAS/CART,24.395,27.895,-10,0,-1,0
PTMEAS/CART,21.92,26.87,-10,0.707,-0.707,0
PTMEAS/CART,20.895,24.395,-10,1,0,0
PTMEAS/CART,21.92,21.92,-10,0.707,0.707,0
PTMEAS/CART,24.395,20.895,-10,0,1,0
PTMEAS/CART,26.87,21.92,-10,-0.707,0.707,0

Click: 'Apply' then 'OK' to complete the measuring cycle.

Click: 'Construct'.



Select: 'Line'.



Make a note of the order the holes have been inserted in the construction window.

i.e. DATUM_X_Y to DAT_X_CIR2 will give a positive direction
and DAT_X_CIR2 to DATUM_X_Y will give a negative direction

This is important when selecting the axis direction for alignment.


Click: 'APPLY' to complete the construction cycle.

Code produced:

F(X_LINE)=FEAT/LINE,UNBND,CART,12.198,12.198,-8.5,0.704,0.704,-0.087,0.061,0.061,0.996

CONST/LINE,F(X_LINE),BF,FA(DATUM_X_Y),FA(DAT_X_CIR2)


Execute a program from the current probe position (non-CAD)



In this case
TOP_FACE_DATUM_C
is the PRIMARY AXIS [+Z]
on drawing datum C

X_LINE is the
SECONDARY AXIS [+X]
(no origin here)
on drawing datum A

DATUM_X_Y
is the TERTIARY
point origin [X and Y]
on drawing datum B



In this case the constructed
line lies along the X axis.

NOTE: There is the option of
selecting -X or +Y/-Y.

Click: 'OK' to complete the procedure


Now check if both circles are in the correct positions

Left mouse click on DATUM_X_Y. The grid will display the result both X and Y should be at zero.



Left mouse Click on DAT_X_CIR2. The grid will display the result:
X = approx 34.50: Radial distance From DATUM_X_Y
Y = 0.00






Now make a theoretical rotation using the defined angle through the 2 co-ordinates given ie:-

$X = 24.395$ and $Y = 24.395$


Angle = $\text{Inv Tan} (24.395 / 24.395) = 45^\circ$

In this case to rotate the X and Y axes clockwise by 45° .

NOTE: -ve angles give clockwise rotation, +ve angles give anti-clockwise rotation.




Enter a label for the final alignment and enter the required angle of rotation.



Now check if both circles are in the correct positions.

Left mouse click on DATUM_X_Y. The grid will display the result, both X and Y should still be at zero.



Left mouse click on DAT_X_CIR2. The grid will display the result:

X = 24.394

Y = 24.394



THE PART ALIGNMENT IS NOW COMPLETE AND IT IS READY FOR MEASUREMENT

Renishaw plc
New Mills, Wotton-under-Edge,
Gloucestershire, GL12 8JR
United Kingdom

T +44 (0)1453 524524
F +44 (0)1453 524901
E uk@renishaw.com
www.renishaw.com

RENISHAW 
apply innovation™

**For worldwide contact details,
please visit our main web site at
www.renishaw.com/contact**



H - 1000 - 5319 - 01